


---

# Removal and Refurbishment (R & R) of the PHENIX Experiment at 1008



Weekly Planning Meeting:8/4/16

Paul Giannotti

# PHENIX This Week

---

- 1. Continue de-cabbling and rack removal on East Carriage.**
- 2. All cooling lines on CM and MMS blown out**
- 3. 3rd Floor EC Platforms down**
- 4. Move MMS and CM South**
- 5. Take down East DC and PC1**

# Next Week at PHENIX

---


1. Remove racks and platforms on 2<sup>nd</sup> floor of EC
2. Continue to remove racks and cable from MMS
3. Erect scaffold between CM and MMN
4. Remove BBC North, MPC-ex North

# Decommissioning Schedule

Major Tasks	Start Date	Finish Date
R&R Engineering, Prep and Planning	In Progress	6/30/16
Initial Tasks Following Run 16	Complete	Complete
Disassemble East Carriage	In Progress	11/4/16
Remove Beampipe/replace with temp pipes	8/30/16	11/30/16
Disassemble Muon Magnet South	8/1/16	12/30/16
Disassemble Central Magnet		
Part 1 (things that can be done early)	8/1/16	12/30/16
Part 2 (everything else)	6/30/17	11/10/17
Disassemble West Carriage		
Part 1 (things that can be done early)	8/1/16	12/30/16
Part 2 (everything else)	7/28/17	11/17/17
Disassemble Muon Magnet North		
Part 1 (things that can be done early)	8/1/16	12/30/16
Part 2 (everything else)	9/25/17	3/9/17
R&R Support Structures		
Part 1 (things that can be done early)	8/1/16	12/30/16
Part 2 (everything else)	6/30/17	9/30/17

Detailed Schedules for each of these major tasks to be determined and detailed on separate slides










### Injuries Per Week (FY) As of 7/29/2016



**Injury Status:**

FY16 YTD: DART – 11, TRC – 23, First Aid – 30  
 FY15: DART – 15, TRC – 25, First Aid – 50  
 FY14: DART – 18, TRC – 34, First Aid – 37

**FY16 Injury Listing:**

<https://shsd.bnl.gov/occinj/BNLIInjuries.aspx>

Recent Injuries		
		None to report

Recent Events		
7/26/16	Non-Reportable	A lab technician overfilled a liquid nitrogen dewar resulting in an ODH monitor alarm. The operation was suspended and the lab space vacated until the alarm reset. Occupants in adjacent spaces were notified and left the building as a precaution.